




x2




x1



x1



x2




x2



x6





x16



$$d = \frac{L_0 + 2z}{3}$$

$$z = 40$$





$$[z = 1\frac{9}{16}]$$




$$d = \frac{L_0 + (n-1) \cdot z}{n}$$

$$z = 40$$


$$[z = 1\frac{9}{16}]$$




L ₀ [mm]	1200	1500	1800	2000	2400	2700
L ₀ [in]	47	59	70	78	95	106
n	3	3	4	4	4	5



4a




4b




5


d [mm]	<500	≥500
d [in]	<20	≥20
n	2	3




6





7






9



10



a

SU5314

